



8/10/2010 COLLIN 6208-44-001 US0075 \$362,276
REPAIR/REPLACE CONCRETE BARRIER

Sheet Title

Sheet Title

- 1 TITLE SHEET
- 2 ESTIMATE & QUANTITY SHEET
- 3A&3B GENERAL NOTES
- 3C GENERAL NOTES
- 4 SUMMARY SHEET
- 5 US 75 TYPICAL PRECAST CTB REPAIR DETAIL
- 6 US 75 CIP CTB REPAIR DETAIL
- 7 BC(1)-07
- 8 BC(2)-07
- 9 BC(3)-07
- 10 BC(4)-07
- 11 BC(5)-07
- 12 BC(6)-07
- 13 BC(7)-07
- 14 BC(8)-07
- 15 BC(9)-07
- 16 BC(10)-07
- 17 BC(11)-07
- 18 BC(12)-07
- 19 TCP(1-2)-98
- 20 TCP(6-1)-98A
- 21 CSB(4)-04
- 22 PCTB(1)-04
- 23 PCTB(2)-04

r = Revised Sheet

Total Sheets in Plan Set: 24